


Dannebrog Auto Service
 114 Roger Welsch Avenue
 Dannebrog, Nebraska

- Monitoring Well Location
- 0.448 Benzene Concentration (mg/L)
- Estimated Benzene Isocentour
- ⊕ Pump Test Recovery Well
- ⊖ Pilot Test Recovery Well
- ⊗ Pilot Test Observation Well
- ⊘ Former USF
- ⊙ Former Product Dispenser
- ⊚ Water Line
- ⊛ Sanitary Sewer
- ⊜ Overhead Electric
- ⊝ Underground Telephone
- ⊞ Gas Line
- ⊟ Utility Access
- ⊠ Utility Pole

**Benzene
 Isoconcentration Map**



Date: 07/28/10
 TSG# 092500-QK-1545

Prepared by: SPC
 Reviewed by:

