


Dannebrog Auto Service  
 114 Roger Welsch Avenue  
 Dannebrog, Nebraska

Date: 07/28/10  
 TUG# 092500-QK-1545

- 85.23 ● Monitoring Well Location
- Groundwater Elevation
- Estimated Groundwater Isocontour
- + Pump Test Recovery Well
- + Pump Test Observation Well
- + Pilot Test Recovery Well
- + Pilot Test Observation Well
- X Former USF
- X Former Product Dispenser
- X Water Line
- X Sanitary Sewer
- X Overhead Electric
- X Underground Telephone
- X Gas Line
- X Utility Access
- X Utility Pole

Groundwater  
 Contour Map



rdg | Geoscience &  
 Engineering